Property Condition Report

Case Number: 093-557144 Contract Area: A8

Current Step:

1c-Ready to Show Condition

2529 FLAGAMI LANE

Step Date:

Address:

04/09/2016

City, St Zip: NORTH PORT, FL 34286-0000

HOC:	Atlanta
------	---------

Allai	πα					
Property Condition Report						
Item Description/Condition		Item Functionality		Functionality/Test Notes		
Cooling/Air-ConditionerHeating/Furnace:HVAC System Duct:	r: OK OK OK	HVAC tested and functional?:	No	The HVAC system was not powered due to electrical system unsafe		
Electrical Wiring:Other:Other:	Damaged OK OK	Electric supply tested and functional?:	No	The electrical system was not powered due to notion from city not to connect power to the house.		
Stove/Range/Oven:Kitchen Cabinets:Other:	Missing OK OK	Built-in appliances tested and functional?:	No	All built in appliances have no apparent deficiencies were revealed at inspection		
Plumbing: Sink: Other:	Damaged OK OK	Water supply tested and functional?:	No	Active pressure was applied with a compressor to the plumbing system and it did not hold pressure indicating a leak in the system. air leaking a well		
Water Heater:	ОК	Water heater functional?:	Yes	The water was not active and our assessment of the water heater revealed no apparent deficiencies at the time of the inspection		
Sewer/Septic System:Toilet:Other:	OK OK OK	Sanitary & plumbing system functional?:	Yes	The water was not active and our assessment of the sewage system revealed no apparent deficiencies at the time of the inspection		
Roof: Other:	OK OK	Roofing in acceptable condition?:	Yes	Our assessment of the roof revealed the shingles on the structure to be in fair condition		